

Transportation

NICHOLAS J. TENNYSON

November 23, 2016

SUBJECT: ADDENDUM 2 FOR DE00166, I-5843, Structure and Signing Rehabilitation on

I-85 in Granville County, WBS Elements: 44851.3.1

MEMORANDUM TO PROSPECTIVE BIDDERS

It has been brought to my attention that there is an error in the unit of measure for the pay item "Elastomeric Joint Header Repair". This item should be paid for as SF (as per the plans and special provision) not SY. Please find attached revised bid sheets.

In addition, there have been concerns over the warranty requirements for the HRCSA. Please note the following changes to the special provisions:

On page ST-33, OMIT (6) under the "Submittals" section (N). This documentation will NOT be required.

On page ST-37, REMOVE the second sentence of the "Penetrant and Paint System".

On page ST-44 and 45, OMIT the "Warranty" section. Please note, the 12-month observation period (see page ST-3) applies to the HRCSA.

As a result of this change the bid opening is DELAYED to 2:00 PM on Wednesday, November 30, 2016.

Please submit bid on revised bid sheets and acknowledge receipt of Addendum 2 in the proposal, if you are submitting a paper bid. This information will also be posted electronically on our website.

If bids are being prepared electronically a **NEW** .EBS file for bid preparation has been provided. Please DELETE the original EBS issued for the project. The new .ebs file has been uploaded to Bid Express to facilitate electronic bidding. For questions, please contact me at (919) 220-4600.

Sincerely,

DocuSigned by:

Jennifer A. Evans, PE

Local Projects Manager

cc: A. Shapiro

B. Tharrington

J. Sandor

R. Roach

T. Sherrill

B. Sloan

M. Biedell

ITEMIZED PROPOSAL FOR CONTRACT NO. DE00166

County: Vance, Granville

Line #	Item Number	Sec #	Description	Quantity	Unit Cost	Amount
		R	COADWAY ITEMS			
0001	0000100000-N	800	MOBILIZATION	Lump Sum	L.S.	
0002	4048000000-E	902	REINFORCED CONCRETE SIGN FOUN- DATIONS	29		
				CY		
0003	4054000000-E	902	PLAIN CONCRETE SIGN FOUNDA- TIONS	2 CY		
0004	4060000000-E	903	SUPPORTS, BREAKAWAY STEEL BEAM	24,357		
				LB		
0005	4096000000-N	904	SIGN ERECTION, TYPE D	7 EA		
			OLON EDECTION TYPE ***			
0006	4110000000-N	904	SIGN ERECTION, TYPE *** (GROUND MOUNTED) (A)	32 EA		
0007	4110000000-N	904	SIGN ERECTION, TYPE ***	23		
			(GROUND MOUNTED) (B)	EA		
0008	4152000000-N	907	DISPOSAL OF SIGN SYSTEM, STEEL	23		
			BEAM	EA		
0009	4155000000-N	907	DISPOSAL OF SIGN SYSTEM, U-	1		
			CHANNEL	EA		
0010	4236000000-N	907	DISPOSAL OF SIGN, A, B OR C	14		
			(GROUND MOUNTED)	EA		
0011	4238000000-N	907	DISPOSAL OF SIGN, D, E OR F	4		
				EA		
0012	4399000000-N	1105	TEMPORARY TRAFFIC CONTROL	Lump Sum	L.S.	
0013	4510000000-N	SP	LAW ENFORCEMENT	250		
				HR		
0014	8296000000-N	442	POLLUTION CONTROL	Lump Sum	L.S.	
0015	8664000000-E	SP	SHOTCRETE REPAIRS	280		
				CF		
0016	8678000000-E	SP	EPOXY RESIN INJECTION	520 LF		
			OFNEDIO OTDUOTUDE ITEM			
0017	886000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & REPAINTING OF BRIDGE #35)	Lump Sum	L.S.	

County: Vance, Granville

Line #	Item Number	Sec #	Description	Quantity	Unit Cost	Amount
0018	8860000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & REPAINTING OF BRIDGE #44)	Lump Sum	L.S.	
0019	8860000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & REPAINTING OF BRIDGE #50)	Lump Sum	L.S.	
0020	886000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & REPAINTING OF BRIDGE #54)	Lump Sum	L.S.	
0021	886000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & REPAINTING OF BRIDGE #57)	Lump Sum	L.S.	
0022	886000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & REPAINTING OF BRIDGE #60)	Lump Sum	L.S.	
0023	886000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & REPAINTING OF BRIDGE #61)	Lump Sum	L.S.	
0024	886000000-N	SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #35)	Lump Sum	L.S.	
0025	886000000-N	SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #44)	Lump Sum	L.S.	
0026	886000000-N	SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #50)	Lump Sum	L.S.	
0027	8860000000-N	SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #51)	Lump Sum	L.S.	
0028	886000000-N	SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #52)	Lump Sum	L.S.	
0029	8860000000-N	SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #54)	Lump Sum	L.S.	
0030	886000000-N	SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #55)	Lump Sum	L.S.	

County: Vance, Granville

86000000-N 86000000-N	SP SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #56)	Lump Sum	L.S.	
		(PAINTING CONTAINMENT FOR	Lump Sum	L.S.	
86000000-N	 SP				
	٠.	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #57)	Lump Sum	L.S.	
86000000-N	SP	GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #60)	Lump Sum	L.S.	
86000000-N			Lump Sum	L.S.	
867000000-E	SP	GENERIC STRUCTURE ITEM (REPLACEMENT OF FOAM JOINT SEAL)	336 LF		
 889000000-E	SP	GENERIC STRUCTURE ITEM (BEAM REPAIR)	4,277 LB		
892000000-E	SP	GENERIC STRUCTURE ITEM (ELASTOMERIC JOINT HEADER REPAIRS)	4 SF		
892000000-E	SP	GENERIC STRUCTURE ITEM (EPOXY COATING)	3,666 SF		
897000000-N	SP		72 EA		
897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #44)	88 EA		
897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #50)	40 EA		
897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51)	36 EA		
897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #52)	36 EA		
897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #54)	40 EA		
- 8 - 8 - 8 - 8 - 8 - 8 - 8 - 8 - 8 - 8	367000000-N 367000000-E 389000000-E 392000000-E 397000000-N 397000000-N 397000000-N	360000000-N SP 367000000-E SP 392000000-E SP 392000000-E SP 397000000-N SP 397000000-N SP 397000000-N SP	(PAINTING CONTAINMENT FOR BRIDGE #60) SP GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #61) SP GENERIC STRUCTURE ITEM (REPLACEMENT OF FOAM JOINT SEAL) SP GENERIC STRUCTURE ITEM (BEAM REPAIR) SP GENERIC STRUCTURE ITEM (BEAM REPAIR) SP GENERIC STRUCTURE ITEM (ELASTOMERIC JOINT HEADER REPAIRS) SP GENERIC STRUCTURE ITEM (ELASTOMERIC JOINT HEADER REPAIRS) SP GENERIC STRUCTURE ITEM (EPOXY COATING) SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #35) SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #44) SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #50) SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #52)	(PAINTING CONTAINMENT FOR BRIDGE #60) Lump Sum (PAINTING CONTAINMENT FOR BRIDGE #61) 167000000-N SP GENERIC STRUCTURE ITEM (REPLACEMENT OF FOAM JOINT SEAL) 336 (REPLACEMENT OF FOAM JOINT SEAL) 189000000-E SP GENERIC STRUCTURE ITEM (BEAM REPAIR) 4,277 LB 192000000-E SP GENERIC STRUCTURE ITEM (ELASTOMERIC JOINT HEADER REPAIRS) 4 192000000-E SP GENERIC STRUCTURE ITEM (ELASTOMERIC JOINT HEADER REPAIRS) 3,666 SF 197000000-N SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/HRCSA BRIDGE #35) 72 CLEANING & PAINTING EXISTING BEARINGS W/HRCSA BRIDGE #44) 197000000-N SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/HRCSA BRIDGE #50) 40 CLEANING & PAINTING EXISTING BEARINGS W/HRCSA BRIDGE #50 197000000-N SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/HRCSA BRIDGE #51) 36 CLEANING & PAINTING EXISTING BEARINGS W/HRCSA BRIDGE #52) 197000000-N SP GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/HRCSA BRIDGE #52) 40 CLEANING & PAINTING EXISTING BEARINGS W/HRCSA BRIDGE #52)	(PAINTING CONTAINMENT FOR BRIDGE #60) 160000000-N SP GENERIC STRUCTURE ITEM (PAINTING CONTAINMENT FOR BRIDGE #61) 167000000-E SP GENERIC STRUCTURE ITEM (REPLACEMENT OF FOAM JOINT LF 189000000-E SP GENERIC STRUCTURE ITEM 4,277 LB 199000000-E SP GENERIC STRUCTURE ITEM 4 (BEAM REPAIR) 199000000-E SP GENERIC STRUCTURE ITEM 4 (ELASTOMERIC JOINT SF HEADER REPAIRS) 190000000-B SP GENERIC STRUCTURE ITEM 3,666 (EPOXY COATING) SF 197000000-N SP GENERIC STRUCTURE ITEM 72 (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #36) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #44) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #44) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #44) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #46) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #50) EA 1970000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) 1970000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51) 197000000-N SP GENERIC STRUCTURE ITEM 6LEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #51)

ITEMIZED PROPOSAL FOR CONTRACT NO. DE00166

Page 4 of 4

County: Vance, Granville

Line #	Item Number	Sec #	Description	Quantity	Unit Cost	Amount
0045	8897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #55)	60 EA		
0046	8897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #56)	60 EA		
0047	8897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #57)	48 EA		
0048	8897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #60)	48 EA		
0049	8897000000-N	SP	GENERIC STRUCTURE ITEM (CLEANING & PAINTING EXISTING BEARINGS W/ HRCSA BRIDGE #61)	48 EA		
0050	8897000000-N	SP	GENERIC STRUCTURE ITEM (STEEL KEEPER ANGLE ASSEMBLY)	11 EA		

1620/Nov22/Q34433.0/D377590100000/E50

Total Amount Of Bid For Entire Project :